Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO1583 Work Order Type: Weatherization **Audit Name:** 14014SO1583

CLIENT INFORMATION

Client Name: 14014SO1583 Address: , Unit 1324

Columbia, TN 38401 Client ID: 14014SO1583

Alt. Client ID: Maury

CLIENT CONTACT INFORMATION

14014SO1583 Applicant/Person of **V**

Record

AGENCY INFORMATION

Agency Phone: (931) 433-7182 **Agency:** South Central Human Resource Agency

Address: 1437 Winchester Highway Fax: (931) 438-0074

> Fayetteville, TN 37334 Email Address:

Agency Contact: Ford, Duane Work Phone:

> Cell Phone: (615) 308-7878 Email Address: Fordd@hughes.net

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Older home in fair cond. Partial basement.

Client Name: 14014SO1583 Client ID: 14014SO1583 Alt. Client ID: Maury

Work Order (Bid Form)

DOE Weatherization Assistant Work Order Name: 14014SO1583 Version 8.5.0 Report Run On: 5/14/2010 Page 1 of 7

Measures

	Measure	1	Infilt	tration Re	edctn				Compone	ents				Inspected
C	omment	2. 3. 4. 5. 6. 7. 8. 9. 10	Repa Air se Air se Seal a Re-gl Air se Air se Repa). Foal . Clea	air broken eal front deal attic acaround acaroun	ccess. c units. l windows ar	nd candow	in back		S.					
									Estimat	ed			Actual	
#	Material /	La	bor	Descripti	on / Comment	•	Units	Qty	Unit Cost	t	Total	Qty	Unit Cost	Total
1	Miscellar Supplies	ieo	us	Infiltratio	n Reduction		Each	1						
2	Labor			Lab or			Hour	6						
C	Other Detai	1												
								Measur	e Sub Total	:		,	Sub Total:	
	Field Note	es:												

Report Run On: 5/14/2010

Heating Equipment Labor Each 2 Cother Detail Measure 3 User-Spec Ceiling R Comment Sq. ft. is estimated. Contractor to verify 100% coverage of R30 prior to bid. Estimated Material / Labor Description / Comment Insulation Attic Insulation - Blown Fiberglass - R-11 Actual Actual Page 1 Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost Total Fiberglass - R-11	N		istall Window Heatpump w trip & AC	/ Aux. He	at	Componen	ts Wall,\	Window	1	Inspecte
# Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost Total Heating Equipment Each 2	Co	omment								
1 Heating Equipment Equipment 2 Labor Labor Each 2						Estimated	<u> </u>		Actual	
Equipment 2 Labor Labor Each 2	#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Measure 3 User-Spec Ceiling R Components Attic Inspector Comment Sq. ft. is estimated. Contractor to verify 100% coverage of R30 prior to bid. Estimated Actual Material / Labor Attic Insulation - Blown Fiberglass - R-11 Other Detail Measure Sub Total: Sub Total: Inspector SqFt 972 Measure Sub Total: Measure Sub Total: Sub Total:			Heatpump	Each	2					
Measure 3 User-Spec Ceiling R Components Attic Comment Sq. ft. is estimated. Contractor to verify 100% coverage of R30 prior to bid. Estimated Actual Material / Labor Attic Insulation Attic Insulation - Blown Fiberglass - R-11 2 Labor Attic Insulation - Blown Fiberglass - R-11 Other Detail Measure Sub Total: Sub Total: Sub Total: Sub Total: Sub Total:	2	Labor	Labor	Each	2					
Field Notes: Measure 3 User-Spec Ceiling R Components Attic Inspector Comment Sq. ft. is estimated. Contractor to verify 100% coverage of R30 prior to bid. Estimated Actual Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost Total Total Total Cost Total	0	ther Detail								
Field Notes: Measure 3 User-Spec Ceiling R Components Attic Inspector Comment Sq. ft. is estimated. Contractor to verify 100% coverage of R30 prior to bid.										
Field Notes: Measure 3 User-Spec Ceiling R Components Attic Inspector Comment Sq. ft. is estimated. Contractor to verify 100% coverage of R30 prior to bid.										
Measure 3 User-Spec Ceiling R Components Attic Inspec Comment Sq. ft. is estimated. Contractor to verify 100% coverage of R30 prior to bid					Measur	e Sub Total:			Sub Total:	
Measure 3 User-Spec Ceiling R Components Attic Inspec Comment Sq. ft. is estimated. Contractor to verify 100% coverage of R30 prior to bid. Estimated Actual # Material / Labor Description / Comment Insulation Attic Insulation - Blown Fiberglass - R-11 SqFt 972 972 2 Labor Attic Insulation - Blown Fiberglass - R-11 SqFt 972 SqFt Other Detail Measure Sub Total: Sub Total:		Field Notes:								
1 Insulation Attic Insulation - Blown Fiberglass - R-11 2 Labor Attic Insulation - Blown Fiberglass - R-11 Other Detail Measure Sub Total: SqFt 972 Measure Sub Total:										
Fiberglass - R-11 2 Labor Attic Insulation - Blown SqFt 972 Fiberglass - R-11 Other Detail Measure Sub Total: Sub Total:	N		-	verify 10	0% co	verage of R	30 prior t	o bid.		Inspecte
Piberglass - R-11 Other Detail Measure Sub Total: Sub Total:	N Co	omment Sq. ff	t. is estimated. Contractor to			verage of R	30 prior t		Actual	Inspecte
Measure Sub Total: Sub Total:	M Co	omment Sq. ft	t. is estimated. Contractor to **Description / Comment** Attic Insulation - Blown	Units	Qty	verage of R	30 prior t		Actual	
	N C c t t 1	omment Sq. fi Material / Labor Insulation	Description / Comment Attic Insulation - Blown Fiberglass - R-11 Attic Insulation - Blown	<i>Units</i> SqFt	Qty 972	verage of R	30 prior t		Actual	
	# 1	omment Sq. fi Material / Labor Insulation Labor	Description / Comment Attic Insulation - Blown Fiberglass - R-11 Attic Insulation - Blown	<i>Units</i> SqFt	Qty 972	verage of R	30 prior t		Actual	
	# 1	omment Sq. fi Material / Labor Insulation Labor	Description / Comment Attic Insulation - Blown Fiberglass - R-11 Attic Insulation - Blown	<i>Units</i> SqFt	Qty 972	verage of R	30 prior t		Actual	
Field Meteo.	# 1	omment Sq. fi Material / Labor Insulation Labor	Description / Comment Attic Insulation - Blown Fiberglass - R-11 Attic Insulation - Blown	<i>Units</i> SqFt	Qty 972	verage of R	30 prior t		Actual	
Field Notes:	# 1	omment Sq. fi Material / Labor Insulation Labor	Description / Comment Attic Insulation - Blown Fiberglass - R-11 Attic Insulation - Blown	Units SqFt SqFt	Qty 972 972	Verage of R Estimated Unit Cost	30 prior t	Qty	Actual Unit Cost	

<i>Measure</i> 4 Re _l Comment	place Back Door Unit, W\$	S, DS, Lo	ck	Componen	ts Door			Inspecte
				Estimated	•		Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Doors	Replace back Door Unit, WS, DS, Lock	Each	1					
Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
•	place Side Door Unit, WS	, DS, Loc	:k	Componen Estimated			Actual	Inspecte
Comment	place Side Door Unit, WS Description / Comment	, DS, Loc	ck 	•		Qty		
Comment Material / Labor				Estimated		Qty	Actual	
Comment Material / Labor Doors	Description / Comment Replace side door Unit,	Units	Qty	Estimated		Qty	Actual	
Comment Material / Labor Doors Labor	Description / Comment Replace side door Unit, WS, DS, Lock	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Doors	Description / Comment Replace side door Unit, WS, DS, Lock	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	Inspecte Total
# Material / Labor Doors Labor	Description / Comment Replace side door Unit, WS, DS, Lock	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
# Material / Labor 1 Doors 2 Labor	Description / Comment Replace side door Unit, WS, DS, Lock	Units Each Hour	Qty 1	Estimated			Actual	

Client Name: 14014SO1583 Client ID: 14014SO1583 Alt. Client ID: Maury

Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0 Page 4 of 7

Measure 6 DW	H Pipe Insulation			Componen	ts DWH		ı	Inspected
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
	All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	or Ins. R-19 is estimated. Contractor to	o verify 10		Component overage. Inc Estimated	luding ad		ment Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	972					
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	972					
Other Detail]							
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Client Name: 14014SO1583 Client ID: 14014SO1583 Alt. Client ID: Maury Work Order (Bid Form)
Work Order Name: 14014SO1583

DOE Weatherization Assistant Version 8.5.0 Page 5 of 7

Report Run On: 5/14/2010

		mproper Venting of Ba aust Fan	throom		Componen	ts H&S		1	Inspected
C	comment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
				Measur	e Sub Total:] :	Sub Total:	
	Measure 9 Pres	sure Relief Piping Nee	ded		Componen			-	Inspected
		sure Relief Piping Nee	ded		Componen Estimated			Actual	Inspected
C		sure Relief Piping Nee	ded	Qty	•		Qty		Inspected
<i>C</i>	Comment	Description / Comment			Estimated		Qty	Actual	
C # 1	Comment Material / Labor Health and Safety	Description / Comment	Units	Qty	Estimated		Qty	Actual	
C # 1	Material / Labor Health and Safety Items	Description / Comment Pressure relief piping	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Pressure relief piping	Units Each Hour	Qty 1 1	Estimated			Actual	

Measure 10 Smoke/ CO2 Detector Combo				Componen	I	nspected			
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke/CO2 Detector Combo	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail								
				Measur	e Sub Total:] :	Sub Total:	
	Field Notes:								
L									
			Work Or	der Gra	nd Total:		Gran	d Total:	